

**IMMEDIATE
BY FAX/E-MAIL
SPL. MESSENGER**

**Government of Tripura
Office of the District Magistrate & Collector
South Tripura**

NO.F. 4(5)/DM/S/DEV/2011/ 875

Dated, the 23rd March, 2011

NOTE

Along with Executive Engineer, RD, Udaipur and BDO, Matabari I visited Bhubeneswari Temple premises and Matabari temple premises from 11:30 a.m to 2:30 p.m on 19.3.2011. Accordingly following actions shall be taken by all concerned:-

BHUBENSWARI TEMPLE:

- As instructed by me, pucca drain together with pucca staircase shall be constructed by the Executive Engineer, RD, Udaipur from Bhubeneswari temple running down to the river bank which has got historical/ archeological/ Tourists' interests. The work could be undertaken by EE, RD, Udaipur out of MGNREGA. BDO would place the money out of available MGNREGA fund to EE, RD, Udaipur (**Action: BDO, Matabari/ EE, RD, Udaipur**)
- IAY houses have been sanctioned for 12 families who have took shelter in the khash land at the Bhubeneswari temple complex i.e. on the river bank side. Since decision is being taken to shift these families to the nearby location. The tilla land for resettlement has been largely leveled down by cutting of earth under MGNREGA from time to time. The balance work which is a part of the tilla land shall have to be undertaken for levelling by using mechanical device. Moreover road formation shall also have to be done by mechanical device. EE, RD, Udaipur may prepare estimate for the same. Sanction would be accorded and fund placed to EE, RD, Udaipur from DM's Office out of interest fund of BDO's lying in bank account under the disposal of Senior Deputy Magistrate. O/C Development shall process the file accordingly. (**Action: O/C DEV/ Sr. Dy. Magistrate/ EE, RD, Udaipur/ BDO, Matabari**)
- As soon as the land levelling work is complete together with road formation work, IAY house construction works should be started immediately by BDO, Matabari and completed including shifting of the families within April, 2011. (**Action: BDO, Matabari**)
- One mini deep tube well should be sunk for these families as also for nearby cultivable land for irrigation under MGNREGA by BDO, Matabari. (**Action: BDO,MTB**)


(Signature)

- Power connection under RGGVY would be taken up by the DGM, TSECL concerned. Additional General Manager TSECL may look into this. This is most important.
(Action: AGM, TSECL)

MATABARI TEMPLE:

- Executive Engineer, RD, Udaipur has already constructed cover drain linking one side of the main entry gate of the Matabari Temple itself to the open space beyond the temple base platform so that water accumulating inside the temple is drained out through the drainage system of Matabari temple complex. 1/2 tiles at the entry gate of the temple is to be replaced by EE, RD, Udaipur at the earliest, as discussed during the visit.
(Action: EE, RD, UDP)
- Around half portion of the old Matabari office on the north eastern corner of the temple tilla would be dismantled so as to construct pucca staircase down to the newly constructed kitchen on the north-eastern slope of the temple tilla for the purpose of taking cooked prasad to the temple itself everyday as a part of the puja. The entire work would be done by EE, RD out of available fund under tourism project. In case of any difficulty in availing the fund, the same would be made available from other sources including MGNREGA/ Matabari Development fund as per procedure.
(Action: EE, RD, UDP/ O/C DEVI/ O/C MGNREGA)

2. ADM & Collector, South/ OSD may follow up to the implementation of the above decisions with different sections of this Collectorate under their respective supervisory assignments.


22-3-11

(SAMARJIT BHOWMIK)

District Magistrate & Collector
South Tripura, Udaipur

To

1. The OSD, DM Office, South Tripura
2. The ADM & Collector, South Tripura.
3. The Officer-in-charge MGNREGA
4. The Additional General Manager, TSECL, Banduar
5. The Senior Deputy Magistrate, DM's Office, South.
6. The Officer-in-charge Development Section DM Office
7. The DIO, NIC South Tripura. He is also requested to upload the same in the District website.
8. The Executive Engineer, RD, Southern Division, Udaipur
9. The Block Development Officer, Matabari RD Block.